

HISTORIC AMERICAN ENGINEERING RECORD  
INDEX TO PHOTOGRAPHS

DELAWARE & RARITAN CANAL: LOCK 6A  
Between Greenwood and Hamilton Avenues  
Trenton  
Mercer County  
New Jersey

HAER NO. NJ-62

HAER  
NJ  
11-TRENTON  
38-

Photographer: Anthony Masso

July 1988

- NJ-62-1 VIEW LOOKING SOUTHEAST FROM UPSTREAM END OF LOCK
- NJ-62-2 VIEW LOOKING SOUTHEAST FROM JUST ABOVE THE UPSTREAM GATES.
- NJ-62-3 VIEW LOOKING SOUTH ACROSS PORTION OF FOREBAY TOWARD REGULATING WEIR AND OVERFLOW INTAKES; UPSTREAM LOCK GATE REMAINS ARE AT RIGHT.
- NJ-62-4 VIEW LOOKING SOUTH AT REGULATING WEIR AND OVERFLOW INTAKES.
- NJ-62-5 VIEW LOOKING EAST AT OVERFLOW INTAKES AND REGULATING WEIR; LOCATION FOR GATE STRUCTURE IS AT LOWER LEFT.
- NJ-62-6 VIEW WITHIN LOCK, LOOKING SOUTH TOWARD UPSTREAM LOCK GATE AND SILL FRAGMENTS.
- NJ-62-7 VIEW LOOKING NORTH FROM BELOW DOWNSTREAM LOCK GATES.
- NJ-62-8 VIEW LOOKING SOUTH TOWARD REMAINS OF DOWNSTREAM GATES.
- NJ-62-9 DOWNSTREAM GATES, DETAIL OF BOTTOM RAILS AT LOCATION OF HEAD POSTS AND TIMBER SILL.
- NJ-62-10 DOWNSTREAM GATES, DETAIL SHOWING CAST IRON WICKETS, BOTTOM RAIL AND FRAGMENT OF HEEL POST.
- NJ-62-11 VIEW TO NORTH ACROSS RAILROAD LINE SHOWING NORTH ABUTMENT OF THE CANAL AQUEDUCT.
- NJ-62-12 VIEW TO SOUTH ACROSS RAILROAD LINE SHOWING SOUTH ABUTMENT OF CANAL AQUEDUCT.